

SECRET

(When Filled In)

FILE INFO

REPRODUCTION PROHIBITED

ACTION	1	6	11	16
	2	7	12	17
	3	8	13	18
	4	9	14	19
	5	10	15	20

NNNT O P S E C R E T 15085Z OCT 71 CITE [REDACTED]

PRIORITY [REDACTED] INFO PRIORITY [REDACTED]

IDEALIST TACKLE

FOR [REDACTED]

SUBJ: MSN C-32 IC

1. AS YOU ARE AWARE THE TRACKER PLOT OF MSN C-32 IC SHOWED THE ARTICLE 10MM WEST OF CRSE AT POINTS D AND F AND ALSO AT LESSER DISTANCES OF 1 TO 5 MM WEST OF COURSE DURING MOST OF THE MISSION. THE TRACKER PLOT WAS DOUBLED CHECKED FOR ACCURACY BY [REDACTED] FLI PLANNERS AND [REDACTED] [REDACTED] FOUND CORRECT.

2. AN ANALYSIS OF THE MSN TRACK WAS PERFORMED TODAY [REDACTED] TO DETERMINE THE REASON FOR THE TRACK ERRORS. THE TRACKER PLOT, [REDACTED] MSN MAP, AND THE [REDACTED] WERE USED.

FOLLOWING ARE THE RESULTS OF BOTH ANALYSES:

A. AT PT B PILOT RECORDED ACTUAL WIND FROM NAV COMPUTER OF 118/35 KNTS. FORECAST WAS 090/25 KNTS. THIS WAS LAST RECORD OF WIND BY PILOT.

SECRET

(When Filled In)

FILE INFO

REPRODUCTION PROHIBITED

ACTION	1	6	11	16
	2	7	12	17
	3	8	13	18
	4	9	14	19
	5	10	15	20

PAGE 2 T O P S E C R E T

READOUT DATA SHOWS ACTUAL POSITION OF ARTICLE AT PT C TO BE 10NM WNW OF PLANNED CRSE POSITION. THIS ERROR CONCLUDED TO BE CAUSED BY STRONGER THAN FORECASTED WIND ON LEG B-C.

C. ALTHOUGH PILOT TURNED 32 SECONDS EARLY AT PT D, ERROR AT PT C AND WINDS STRONGER THAN FORECASTED CAUSED 10NM ERROR AT PTS D AND F. SHOW THAT PILOT NOTED ERROR AT PTS D AND F AND MADE CORRECTIONS TO THE LEFT UP TO 16 DEGREES. HOWEVER, THESE WERE INADEQUATE TO RETURN HIM ALL THE WAY BACK TO CRSE.

D. THE EFFECT OF THE FIRST ERROR AT PT C CONTINUED THROUGHOUT THE FLT ALTHOUGH PILOT CORRECTIONS EVENTUALLY RETURNED HIM TO A PRECISE TRACK ON LEG U-V.

3. AFTER A DETAILED STUDY OF THE MSN DATA IT IS OUR CONCLUSION THAT:

A. THE ERRORS WERE CAUSED BY STRONGER THAN FORECASTED WINDS.

B. THERE WAS NO DELIBERATE ATTEMPT TO DEVIATE FROM THE PLANNED CRSE.

Approved For Release 2003/11/25 : CIA-RDP74B00496R000300110093-2

SECRET

(When Filled In)

FILE INFO

REPRODUCTION PROHIBITED

ACTION	1	6	11	16
	2	7	12	17
	3	8	13	18
	4	9	14	19
	5	10	15	20

PAGE 3 TOP SECRET

C. THE PILOT SHOWED NO LACK OF PORFICIENCY AND
MADE WHAT HE UNDERSTANDABLY THOUGHT WERE PROPER CORRECTIONS
TO RETURN TO COURSE.

 THAT THE ERRORS WERE A RESULT OF UNPREDICTED WINDS.

TOP SECRET

BT

#3386